

HILLER AIRCRAFT CORPORATION 925 "M" STREET/ PO BOX 246 FIREBAUGH CA 93622 PHONE: 559-659-5959 FAX: 559-659-5950

PUBLICATION STATUS ON UH-12E PISTON HELICOPTERS

Service Letters & Bulletins

Service Letter Index

- Service Letter 10-7
- Service Letter 10-10
- Added Service Letter 10-16
- Added Service Letter 10-17
- Service Bulletin Index

Illustrated Parts List

Temp Revision Pg. 63 Temp Revision Pg. 149 Temp Revision Pg. 199 Temp Revision Pg. 219 Temp Revision Pg. 221 Temp Revision Pg. 269 Numerical Index Pg. 425 Numerical Index Pg. 457 Numerical Index Pg. 457 Numerical Index Pg. 489

Service Manual

List of Effective Pages • Temp Rev. Pg. 24-5 Pg. 34-4 Revised Paragraph

- Rev. (Front of Pg. 53-3)
- Rev. Section 24 Change

Flight Manual 3-Place

Flight Manual 4-Place

Instructions for Continued Airworthiness

Structural Repair

January 1, 2019 April 10, 2004 February 16, 2000 December 10, 2009 December 15, 2014 January 1, 2019

September 2017 October 30, 2023 September 1, 2023 May 3, 2023 March 1, 2021 March 1, 2021 May 24, 2023 September, 2022 June, 2022 June, 2022 May 24, 2023

October 1996 June 1, 2018 June 14, 2017 April 26, 2018 December 10, 2009 June 2017

October 1996

October 1996

August 1, 2009

June 1999



HILLER AIRCRAFT CORPORATION 925 "M" STREET/ PO BOX 246 FIREBAUGH CA 93622 PHONE: 559-659-5959 FAX: 559-659-5950

PUBLICATION STATUS ON UH-12E PISTON HELICOPTERS (CONTINUED)

Overhaul Manuals

Main Rotor Transmission Assy Control Rotor Cuff & Trunnion Assy Cooling Fan Gearbox Assy Tail Rotor Assy Tail Rotor Speed Decreaser Gear Assy Cardan Joint Assembly Wobble Plate & Scissors Assy Slip Joint Assy May 2015 February 2017 November 2016 August 1, 2017 July 2015 February 2017 March 25, 2018 June 1, 2018

*List updated 11/17/2023