



HILLER AIRCRAFT CORPORATION
925 "M" STREET/ PO BOX 246
FIREBAUGH CA 93622
PHONE: 559-659-5959 FAX: 559-659-5950

Publication Status ON UH-12D/E Turbine Helicopters

Service Letter Index	December 10, 2009
• Service Letter 05-560	April 10, 2004
• Service Letter 33-560	April 1, 2004
• Service Letter 34-560	December 10, 2009
Service Bulletin Index	January 17, 2005
Parts Manual Supplement	March 1995
Temporary Revision 12-98-560	January 5, 2024
Service Manual	June 1995
Service Instruction Index	June 7, 1990
Flight Manual 3-Place	December 4, 1997
Flight Manual 4-Place	December 4, 1997
Inspection Guide	October 1997
Structural Repair	June 1995
Component Overhaul Manual	June 1995

No changes have been made to these manuals as of January 2024.