

HILLER AIRCRAFT CORPORATION 925 "M" STREET/ PO BOX 246 FIREBAUGH CA 93622

PHONE: 559-659-5959 FAX: 559-659-5950

PUBLICATION STATUS ON UH-12ABC PISTON HELICOPTERS

 SERVICE LETTER INDEX SERVICE LETTER 139 SERVICE LETTER 140 SERVICE LETTER 141 SERVICE LETTER 142 SERVICE LETTER 143 	DECEMBER 15, 2014 APRIL 7, 2004 APRIL 8, 2004 APRIL 10, 2004 DECEMBER 10, 2009 DECEMBER 15, 2014
SERVICE BULLETIN INDEX	MAY 3, 2007
PARTS CATALOG • TEMP REVISION (FRONT OF PG. 35,37,39,41,43)	JANUARY 1997 SEPTEMBER 25, 2002
 SERVICE MANUAL TEMP REVISION (FRONT OF PG. 185,192) REV (FRONT OF PG 72B) 	JANUARY 1, 1997 SEPTEMBER 25, 2002 DECEMBER 10, 2009
UH-12B FLIGHT MANUAL UH-12C FLIGHT MANUAL	MARCH 27, 1952 DECEMBER 9, 1955
INSPECTION GUIDETEMP REVISION (FRONT OF PG. 34)	JANUARY 1, 1997 SEPTEMBER 22, 2002
STRUCTURAL REPAIR	JANUARY 1, 1997
OVERHAUL MANUAL MAIN ROTOR BLADE ASSY	JANUARY 1, 1997
MAIN TRANSMISSION	JANUARY 1, 1997
FAN GEARBOX	JANUARY 1, 1997

MARCH 1, 1973

TAIL ROTOR GEARBOX