



HILLER AIRCRAFT CORPORATION
925 "M" STREET/ PO BOX 246
FIREBAUGH CA 93622
PHONE: 559-659-5959 FAX: 559-659-5950

PUBLICATION STATUS ON BELL 47G TURBINE HELICOPTERS

Service Letter Index	December 10, 2009
• Service Letter 01-660	April 10, 2004
• Service Letter 31-660	December 10, 2009
Service Bulletin Index	May 6, 1985
Illustrated Parts Manual	April 1995
• Temp Revision Page 69	March 30, 2023
Service Instructions	April 19, 1990
• Service Instruction Index	April 8, 2004
• Service Instruction #66015	December 1, 2010
Flight Manual	November 4, 1998
• Flight Manual Revision #30	November 15, 2023
Maintenance & Overhaul Instructions	November 21, 1997
• Page i -660-1-43	April 6, 2005

**Latest Change made on November 15, 2023*